

8005R NCDF KITCHEN

PROJECT UPDATE: 1/28/2021



SOME OF THE DRY ROT



LOCATION OF THE OLD WALK-INS



CUTTING/PEELING CONCRETE



EXCAVATION



SPECIALIZED VAC TRUCK




OPEN TRENCHES WITH NEW PLUMBING




PLUMBING WORK IN PROGRESS



CONCRETE PLACEMENT



CONCRETE PLACEMENT



DRY ROT REPAIRS IN PROGRESS



DRY ROT REPAIRS IN PROGRESS



MORTAR BED DEFICIENCIES

